

**Customer:** City of Coalinga

**Attention:** Anthony

From: Ron Paul

## **Quote P15 Repairs**

Date: 05/04/20

Line	Tax	Qty.	Description	Unit Price	Total
1	N	1	Labor	\$26,025.00	\$26,025.00
2	Υ	1	Materials	\$11,825.00	\$11,825.00
3	Υ	1	Replacement Bowl Assembly	\$61,665.00	\$61,665.00
				•	\$99,515.00
				freight	\$221.95
				tax	\$6,081.24
				•	\$105,818.19

1) disassemble, clean, and inspect for quote 2) replace the bowl assembly, all shafts, all

Job scope: column pipes, and all bushings 3) modify the seal gland to fit a new Chesterton 442 seal 4)

assemble, test, and paint

Amount due if repairs are declined: \$9,950.00

A deposit of \$45,000 will be due prior to the replacement bowl assembly being ordered.

Quoted prices do not include taxes or freight.

Quoted prices are based on the quantities listed.

Quoted prices are subject to raw material price in effect at time of order.

Thank you for the opportunity to quote these services.

sharcraftinc.com 1103 33rd Street Bakersfield, CA 93301

(661) 324-4985